

발전기금 정산서

- 사업명 : [PNU펜토미노 교육과정 개발 지원 사업] 항공우주공학과 전산실습실
- 총사업비 : 89,010,000
- 사용시기 : 2025-01-07 ~ 2025-02-28

지원액	집행액	잔액	사용내역	비고
89,010,000	85,025,920	3,984,080	항공우주공학과 전산실습실 이전 및 대형강의실 구축 총 85,025,920원 1. 강의실 전기공사비 : 13,440,000원 (준이엔지) 2. 강의실용 책상 및 의자 : 33,202,810원(부산지방조달청 2건) 3. 전자교탁 시스템(음향, 빔프로젝트+스크린 3세트 포함) : 35,733,110원 (부산지방조달청 8건) 4. 영상정보디스플레이장치(75인치) : 2,650,000원 (선테크)	

※ 지출 증빙서류 : 10년간 자체 보관

위와 같이 발전(목적)기금 집행 정산서를 제출합니다.

정산자 : 항공우주공학과장



2025. 2. 19

재단법인부산대학교발전기금이사장 귀하

항공관 8308호 (전산실)



2025년 2월 항공우주공학과 발전기금 및 국립대학육성사업으로 전산실습실 이전 : 항공관 8308호실

기전관 9306호 (대형강의실)



2025년 2월 항공우주공학과 발전기금 및 국립대학육성사업으로 대형강의실 조성 : 기전관 9306호실

항공우주공학과 8308호 전산실 이전
및 9306호 대형강의실 전기공사
사진첩

*** 8308호***

*** 8308호 배선 작업***

공사전



공사중



공사후



*** 9306호***

*** 배전함 이전 설치 ***


공사전



공사중



공사후



***** 레이스웨이 및 배선작업 *****


공사전



공사중



공사후



*** 라인조명 작업***

공사전



공사중



공사후



*** 전면 조명설치 ***

공사전



공사중



공사후



준공사진첩

[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사

엘레브



사 진 대 지

공사명	[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사
작업명	철거공사
공사전	
공사중	
공사후	

사 진 대 지

공사명	[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사
작업명	목공사-전면
공사전	 A photograph showing the interior of a room before construction. The walls are made of exposed wooden studs and panels. A window with a wooden frame is visible on the right. The floor is concrete and appears to be in the process of being prepared.
공사중	 A photograph showing the interior of a room during construction. The walls are now covered in light-colored wood paneling. A string of small, round lights is hanging from the ceiling. Two ladders are leaning against the wall on the left. The floor is still concrete.
공사후	 A photograph showing the interior of a room after construction. The walls are finished with light-colored wood paneling. The ceiling is white with recessed lighting. A small table and chairs are visible in the background, suggesting the room is ready for use.

사 진 대 지

공사명	[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사
작업명	목공사 -측면
공사전	
공사중	
공사후	


사 진 대 지

공사명	[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사
작업명	도장공사
공사전	
공사중	
공사후	

사 진 대 지

공사명	[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사
작업명	도장공사
공사전	 A photograph showing the interior of a room before painting. The ceiling is made of concrete with exposed pipes and ductwork. A worker is visible on a scaffold, and a string of lights is hanging from the ceiling.
공사중	 A photograph showing a worker in a white hard hat and black jacket painting the ceiling. The ceiling is covered with a white protective sheet, and the worker is using a long-handled brush to apply paint.
공사후	 A photograph showing the room after painting. The ceiling is now black, and the walls are white. The room is clean and finished, with a window and a string of lights visible.

사 진 대 지

공사명	[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사
작업명	인테리어필름
공사전	
공사중	
공사후	

사 진 대 지

공사명	[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사
작업명	유리공사
공사전	
공사중	
공사후	

사 진 대 지

공사명	[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사
작업명	공사 전
공사전	 A photograph showing the interior of a room before renovation. The ceiling is cluttered with numerous white pipes and black electrical wires. The walls are white with a dark baseboard. There are windows with metal grates. A blue cabinet and a white step ladder are visible in the room.
공사중	 A photograph showing a construction worker in a white hard hat and safety vest working on the ceiling. The worker is standing on a white step ladder, handling a bundle of wires. The room is in a state of active renovation, with wooden planks and other materials on the floor.
공사후	 A photograph showing the room after renovation. The walls are now covered in light-colored wood paneling. The ceiling is clean and modern, with recessed lighting. A blue cabinet with a computer monitor and keyboard is positioned in the room. The overall appearance is clean and organized.

사 진 대 지

공사명	[국립대육성 2-3-1] 항공우주공학과 9306호 환경개선공사
작업명	완료사진
전면	
측면	
후면/ 천정	